

CEMA Safety Label Placement Guidelines

CEMA Safety Labels



Placement Guidelines

Product: Bulk Handling Equipment

Equipment: Vertical Screw Conveyors

USE LABEL "A" ON BELT GUARD

USE LABEL "B" ON ENDS OF TROUGH, ON INTAKE INSPECTION DOOR, AND BOTH SIDES OF DISCHARGE SPOUT



"A"

To be placed on removable guards to warn that operation of the machinery with guards removed would expose chains, belts, gears, shafts, pulleys, couplings, etc. which create hazards



"B"

To be placed on inlets and discharges, troughs, covers, and inspection doors of screw conveyors to provide warning against exposed moving parts while in operation.

